



# STM8S103xx and STM8S903xx Errata sheet

## STM8S103xx and STM8S903xx device limitations

### Silicon identification

This errata sheet applies to the STMicroelectronics STM8S103xx and STM8S903xx devices.

The full list of root part numbers is given in [Table 2](#).

The products can be identified as shown in [Table 1](#):

- By the revision code marked below the sales type on the device package
- By the last three digits of the Internal sales type printed on the box label

**Table 1. Device identification**

Sales type	Revision code marked on the device <sup>(1)</sup>
STM8S103xxxx	Z and Y/6
STM8S903xxxx	Z and Y/6

1. Refer to [Appendix A: Revision code on device marking](#) for details on how to identify the revision code according to the packages.

**Table 2. Device summary**

Part number	Part number
STM8S103xx	STM8S103K3, STM8S103F3, STM8S103F2
STM8S903xx	STM8S903K3, STM8S903F3

# Contents

- 1      Product evolution ..... 3**
- 2      Silicon limitations ..... 4**
  - 2.1    Core limitations ..... 4
    - 2.1.1    Activation level (AL bit) not functional in Halt mode ..... 4
    - 2.1.2    JRIL and JRIH instructions not available ..... 4
    - 2.1.3    Interrupt service routine (ISR) executed with priority of  
main process ..... 4
    - 2.1.4    Unexpected DIV/DIVW instruction result in ISR ..... 5
  - 2.2    Clock controller ..... 6
    - 2.2.1    HSI RC oscillator cannot be switched off in Run mode ..... 6
    - 2.2.2    LSI oscillator remains on in Active halt mode when  
the AWU unit uses the HSE as input clock ..... 6
  - 2.3    UART peripheral limitations ..... 7
    - 2.3.1    UART PE flag cannot be cleared during the reception of  
the first half of Stop bit ..... 7
  - 2.4    I<sup>2</sup>C peripheral limitations ..... 7
    - 2.4.1    I<sup>2</sup>C event management ..... 7
    - 2.4.2    Corrupted last received data in I<sup>2</sup>C Master Receiver mode ..... 8
    - 2.4.3    Wrong behavior of I<sup>2</sup>C peripheral in Master mode after  
misplaced STOP ..... 9
    - 2.4.4    Violation of I<sup>2</sup>C “setup time for repeated START condition” parameter .. 9
    - 2.4.5    In I<sup>2</sup>C slave “NOSTRETCH” mode, underrun errors may not be detected  
and may generate bus errors ..... 10
    - 2.4.6    I<sup>2</sup>C pulse missed ..... 11
- Appendix A    Revision code on device marking ..... 12**
- Revision history ..... 13**

# 1 Product evolution

Table 3 gives a summary of the fix status.

Legend for Table 3: A = workaround available; N = no workaround available; P = partial workaround available, '-' and grayed = fixed.

**Table 3. Product evolution summary**

Section	Limitation	Rev Z	Rev Y/6
Section 2.1: Core limitations	Section 2.1.1: Activation level (AL bit) not functional in Halt mode	N	N
	Section 2.1.2: JRIL and JRIH instructions not available	N	N
	Section 2.1.3: Interrupt service routine (ISR) executed with priority of main process	N	N
	Section 2.1.4: Unexpected DIV/DIVW instruction result in ISR	A	A
Section 2.2: Clock controller	Section 2.2.1: HSI RC oscillator cannot be switched off in Run mode	N	N
	Section 2.2.2: LSI oscillator remains on in Active halt mode when the AWU unit uses the HSE as input clock	N	N
Section 2.3: UART peripheral limitations	Section 2.3.1: UART PE flag cannot be cleared during the reception of the first half of Stop bit	A	A
Section 2.4: I <sup>2</sup> C peripheral limitations	Section 2.4.1: I <sup>2</sup> C event management	A	A
	Section 2.4.2: Corrupted last received data in I <sup>2</sup> C Master Receiver mode	A	A
	Section 2.4.3: Wrong behavior of I <sup>2</sup> C peripheral in Master mode after misplaced STOP	A	A
	Section 2.4.4: Violation of I <sup>2</sup> C "setup time for repeated START condition" parameter	A	A
	Section 2.4.5: In I <sup>2</sup> C slave "NOSTRETCH" mode, underrun errors may not be detected and may generate bus errors	A	A
	Section 2.4.6: I <sup>2</sup> C pulse missed	A	-

## 2 Silicon limitations

### 2.1 Core limitations

#### 2.1.1 Activation level (AL bit) not functional in Halt mode

##### Description

As described in the STM8S microcontroller family reference manual (RM0016), an IRET instruction should switch the device into WFI mode or Halt mode when the AL bit is set.

In STM8S103/903xx devices, the IRET instruction only causes the CPU to enter the WFI mode.

##### Workaround

No workaround available.

#### 2.1.2 JRIL and JRIH instructions not available

##### Description

JRIL (jump if port INT pin = 0) and JRIH (jump if port INT pin = 1) are not supported by the devices covered by this errata sheet. These instructions perform a conditional jump: JRIL and JRIH jump if one of the external interrupt lines is low and high, respectively. JRIL is equivalent to an unconditional jump and JRIH is equivalent to a NOP.

For further details on these instructions, refer to the STM8 CPU programming manual (PM0044) on <http://www.st.com>.

##### Workaround

No workaround available.

#### 2.1.3 Interrupt service routine (ISR) executed with priority of main process

##### Description

If an interrupt is cleared or masked when the context saving has already started, the corresponding ISR is executed with the priority of the main process.

##### Workaround

No workaround available.

## 2.1.4 Unexpected DIV/DIVW instruction result in ISR

### Description

In very specific conditions, a DIV/DIVW instruction may return a false result when executed inside an interrupt service routine (ISR). This error occurs when the DIV/DIVW instruction is interrupted and a second interrupt is generated during the execution of the IRET instruction of the first ISR. Under these conditions, the DIV/DIVW instruction executed inside the second ISR, including function calls, may return an unexpected result.

The applications that do not use the DIV/DIVW instruction within ISRs are not impacted.

### Workaround 1

If an ISR or a function called by this routine contains a division operation, the following assembly code should be added inside the ISR before the DIV/DIVW instruction:

```
push cc
pop a
and a, # $BF
push a
pop cc
```

This sequence should be placed by C compilers at the beginning of the ISR using DIV/DIVW. Refer to your compiler documentation for details on the implementation and control of automatic or manual code insertion.

### Workaround 2

To optimize the number of cycles added by workaround 1, you can use this workaround instead. Workaround 2 can be used in applications with fixed interrupt priorities, identified at the program compilation phase:

```
push #value
pop cc
```

where bits 5 and 3 of #value have to be configured according to interrupt priority given by I1 and I0, and bit 6 kept cleared.

In this case, compiler workaround 1 has to be disabled by using compiler directives.

No fix is planned for this limitation.

## 2.2 Clock controller

### 2.2.1 HSI RC oscillator cannot be switched off in Run mode

#### Description

The internal 16 MHz HSI RC oscillator cannot be switched off in Run mode even if the HSIEN bit is programmed to 0.

#### Workaround

No workaround available.

### 2.2.2 LSI oscillator remains on in Active halt mode when the AWU unit uses the HSE as input clock

#### Description

When the Auto wake-up unit (AWU) uses the high speed external clock (HSE) divided by the prescaler (clock source enabled by setting the CKAWUSEL option bit), the LSI RC oscillator is not switched off when the devices operate in Active halt mode with the main voltage regulator (MVR) on. This causes negligible extra power consumption compared to the total consumption of the MCU in Active Halt mode with main voltage regulator (MVR) on.

#### Workaround

No workaround available.

## 2.3 UART peripheral limitations

### 2.3.1 UART PE flag cannot be cleared during the reception of the first half of Stop bit

#### Description

The PE flag is set by hardware when the UART is in reception mode and a parity error (PE) occurs. This flag cannot be cleared during the first half of the Stop bit period. If the software attempts to clear the PE flag at this moment, the flag is set again by hardware, thus generating an unwanted interrupt (assuming the PIEN bit has been set in the UART\_CR1 register).

#### Workaround

1. Disable PE interrupts by setting PIEN to 0.
2. After the RXNE bit is set (received data ready to be read), poll the PE flag to check if it a parity error occurred. For example, this could be done in the RXNE interrupt service routine.

## 2.4 I<sup>2</sup>C peripheral limitations

### 2.4.1 I<sup>2</sup>C event management

#### Description

As described in the I<sup>2</sup>C section of the STM8S and STM8A microcontroller reference manual (RM0016), the application firmware has to manage several software events before the current byte is transferred. If the EV7, EV7\_1, EV6\_1, EV6\_3, EV2, EV8, and EV3 events are not managed before the current byte is transferred, problems may occur such as receiving an extra byte, reading the same data twice, or missing data.

#### Workaround

When the EV7, EV7\_1, EV6\_1, EV6\_3, EV2, EV8, and EV3 events cannot be managed before the current byte transfer, and before the acknowledge pulse when the ACK control bit changes, it is recommended to use I<sup>2</sup>C interrupts in nested mode and to make them uninterruptible by increasing their priority to the highest priority in the application.

No fix is planned for this limitation.

## 2.4.2 Corrupted last received data in I<sup>2</sup>C Master Receiver mode

### Conditions

In Master Receiver mode, when the communication is closed using method 2, the content of the last read data may be corrupted. The following two sequences are concerned by the limitation:

- Sequence 1: transfer sequence for master receiver when  $N = 2$ 
  - a) BTF = 1 (Data N-1 in DR and Data N in shift register)
  - b) Program STOP = 1
  - c) Read DR twice (Read Data N-1 and Data N) just after programming the STOP bit.
- Sequence 2: transfer sequence for master receiver when  $N > 2$ 
  - a) BTF = 1 (Data N-2 in DR and Data N-1 in shift register)
  - b) Program ACK = 0
  - c) Read Data N-2 in DR
  - d) Program STOP bit to 1
  - e) Read Data N-1.

### Description

The content of the shift register (data N) is corrupted (data N is shifted 1 bit to the left) if the user software is not able to read data N-1 before the STOP condition is generated on the bus. In this case, reading data N returns a wrong value.

### Workarounds

- Workaround 1
  - Sequence 1  
When sequence 1 is used to close communication using method 2, mask all active interrupts between STOP bit programming and Read data N-1.
  - Sequence 2  
When sequence 2 is used to close communication using method 2, mask all active interrupts between Read data N-2, STOP bit programming and Read data N-1.
- Workaround 2  
Manage I2C RxNE and TxE events with interrupts of the highest priority level, so that the condition BTF = 1 never occurs.



### 2.4.3 Wrong behavior of I<sup>2</sup>C peripheral in Master mode after misplaced STOP

#### Description

The I<sup>2</sup>C peripheral does not enter Master mode properly if a misplaced STOP is generated on the bus. This can happen in the following conditions:

- If a void message is received (START condition immediately followed by a STOP): the BERR (bus error) flag is not set, and the I<sup>2</sup>C peripheral is not able to send a START condition on the bus after writing to the START bit in the I2C\_CR2 register.
- In the other cases of a misplaced STOP, the BERR flag is set in the IC2\_CR2 register. If the START bit is already set in I2C\_CR2, the START condition is not correctly generated on the bus and can create bus errors.

#### Workaround

In the I<sup>2</sup>C standard, it is not allowed to send a STOP before the full byte is transmitted (8 bits + acknowledge). Other derived protocols like CBUS allow it, but they are not supported by the I<sup>2</sup>C peripheral.

In case of noisy environment in which unwanted bus errors can occur, it is recommended to implement a timeout to ensure that the SB (start bit) flag is set after the START control bit is set. In case the timeout has elapsed, the peripheral must be reset by setting the SWRST bit in the I2C\_CR2 control register. The I<sup>2</sup>C peripheral should be reset in the same way if a BERR is detected while the START bit is set in I2C\_CR2.

No fix is planned for this limitation.

### 2.4.4 Violation of I<sup>2</sup>C “setup time for repeated START condition” parameter

#### Description

In case of a repeated Start, the “setup time for repeated START condition” parameter (named  $t_{SU(STA)}$  in the datasheet and  $T_{su:sta}$  in the I<sup>2</sup>C specifications) may be slightly violated when the I<sup>2</sup>C operates in Master Standard mode at a frequency ranging from 88 to 100 kHz.  $t_{SU(STA)}$  minimum value may be 4  $\mu$ s instead of 4.7  $\mu$ s.

The issue occurs under the following conditions:

1. The I<sup>2</sup>C peripheral operates in Master Standard mode at a frequency ranging from 88 to 100 kHz (no issue in Fast mode)
2. and the SCL rise time meets one of the following conditions:
  - The slave does not stretch the clock and the SCL rise time is more than 300 ns (the issue cannot occur when the SCL rise time is less than 300 ns).
  - or the slave stretches the clock.

#### Workaround

Reduce the frequency down to 88 kHz or use the I<sup>2</sup>C Fast mode if it is supported by the slave.

## 2.4.5 In I<sup>2</sup>C slave “NOSTRETCH” mode, underrun errors may not be detected and may generate bus errors

### Description

The data valid time ( $t_{VD;DAT}$ ,  $t_{VD;ACK}$ ) described by the I<sup>2</sup>C specifications may be violated as well as the maximum current data hold time ( $t_{HD;DAT}$ ) under the conditions described below. In addition, if the data register is written too late and close to the SCL rising edge, an error may be generated on the bus: SDA toggles while SCL is high. These violations cannot be detected because the OVR flag is not set (no transmit buffer underrun is detected).

This issue occurs under the following conditions:

1. The I<sup>2</sup>C peripheral operates In Slave transmit mode with clock stretching disabled (NOSTRETCH=1)
2. and the application is late to write the DR data register, but not late enough to set the OVR flag (the data register is written before the SCL rising edge).

### Workaround

If the master device supports it, use the clock stretching mechanism by programming the bit NOSTRETCH=0 in the I2C\_CR1 register.

If the master device does not support it, ensure that the write operation to the data register is performed just after TXE or ADDR events. You can use an interrupt on the TXE or ADDR flag and boost its priority to the higher level.

Using the “NOSTRETCH” mode with a slow I<sup>2</sup>C bus speed can prevent the application from being late to write the DR register (second condition).

*Note: The first data to be transmitted must be written into the data register after the ADDR flag is cleared, and before the next SCL rising edge, so that the time window to write the first data into the data register is less than  $t_{LOW}$ .*

*If this is not possible, a possible workaround can be the following:*

1. Clear the ADDR flag
2. Wait for the OVR flag to be set
3. Clear OVR and write the first data.

*The time window for writing the next data is then the time to transfer one byte. In that case, the master must discard the first received data.*

## 2.4.6 I<sup>2</sup>C pulse missed

### Description

When the I<sup>2</sup>C interface is used for long transmit/receive transactions, the MCU may return a NACK somewhere during the transaction instead of returning an ACK for all data. The received data may also be corrupted. In Master mode the I<sup>2</sup>C may not detect an incoming ACK. This is due to a weakness in the noise filter of the I/O pad which in certain conditions may cause the STM8 I<sup>2</sup>C to miss a pulse.

The workaround described below is not a clean solution.

### Workaround

Since data corruption is caused by noise generated by the CPU, CPU activity should be minimized during data reception and/or transmission. This is done by performing physical data transmission (Master mode) and reception (slave mode) in WFI state (wait for interrupt).

To allow the device to be woken up from WFI, I<sup>2</sup>C transmission and reception routines must be implemented through interrupt routines instead of polling mechanisms. Receive and transmit interrupts (received data processing) must be triggered only by the BTF bit flag (byte transfer finished) in the I2C\_SR1 register. This flag indicates that the I<sup>2</sup>C is in stretched state (data transfers are stretched on the bus).

Clock stretching must be enabled to allow data transfers from the slave to be stopped and to allow the CPU to be woken up to read the received byte.

To recover from possible errors, periodically check if the I<sup>2</sup>C does not remain in busy state for too long (BUSY bit set in I2C\_SR3 register). If so, it should be reinitialized.

### Example of I<sup>2</sup>C slave code:


```
//...
//-----
void main()
{
    Init_I2C(); // init I2C to use interrupts: ITBUFEN=0, ITEVTEN=1,
    ITERREN=1
    while(1)
```

## Appendix A Revision code on device marking

The revision code is marked on the package, except for revision Z which is not present on TSSOP20.

*Figure 1* shows the marking for the LQFP32 package.

**Figure 1. LQFP32 top package view**



## Revision history

**Table 4. Document revision history**

Date	Revision	Changes
01-Apr-2010	1	Initial release.
21-Feb-2011	2	Added revision 6. Added <a href="#">Section 2.1.4: Unexpected DIV/DIVW instruction result in ISR.</a> Updated <a href="#">Table 3</a> and <a href="#">Section 2.4: I<sup>2</sup>C peripheral limitations.</a>

**Please Read Carefully:**

Information in this document is provided solely in connection with ST products. STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, modifications or improvements, to this document, and the products and services described herein at any time, without notice.

All ST products are sold pursuant to ST's terms and conditions of sale.

Purchasers are solely responsible for the choice, selection and use of the ST products and services described herein, and ST assumes no liability whatsoever relating to the choice, selection or use of the ST products and services described herein.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted under this document. If any part of this document refers to any third party products or services it shall not be deemed a license grant by ST for the use of such third party products or services, or any intellectual property contained therein or considered as a warranty covering the use in any manner whatsoever of such third party products or services or any intellectual property contained therein.

**UNLESS OTHERWISE SET FORTH IN ST'S TERMS AND CONDITIONS OF SALE ST DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY WITH RESPECT TO THE USE AND/OR SALE OF ST PRODUCTS INCLUDING WITHOUT LIMITATION IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE (AND THEIR EQUIVALENTS UNDER THE LAWS OF ANY JURISDICTION), OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**UNLESS EXPRESSLY APPROVED IN WRITING BY AN AUTHORIZED ST REPRESENTATIVE, ST PRODUCTS ARE NOT RECOMMENDED, AUTHORIZED OR WARRANTED FOR USE IN MILITARY, AIR CRAFT, SPACE, LIFE SAVING, OR LIFE SUSTAINING APPLICATIONS, NOR IN PRODUCTS OR SYSTEMS WHERE FAILURE OR MALFUNCTION MAY RESULT IN PERSONAL INJURY, DEATH, OR SEVERE PROPERTY OR ENVIRONMENTAL DAMAGE. ST PRODUCTS WHICH ARE NOT SPECIFIED AS "AUTOMOTIVE GRADE" MAY ONLY BE USED IN AUTOMOTIVE APPLICATIONS AT USER'S OWN RISK.**

Resale of ST products with provisions different from the statements and/or technical features set forth in this document shall immediately void any warranty granted by ST for the ST product or service described herein and shall not create or extend in any manner whatsoever, any liability of ST.

ST and the ST logo are trademarks or registered trademarks of ST in various countries.

Information in this document supersedes and replaces all information previously supplied.

The ST logo is a registered trademark of STMicroelectronics. All other names are the property of their respective owners.

© 2011 STMicroelectronics - All rights reserved

STMicroelectronics group of companies

Australia - Belgium - Brazil - Canada - China - Czech Republic - Finland - France - Germany - Hong Kong - India - Israel - Italy - Japan - Malaysia - Malta - Morocco - Philippines - Singapore - Spain - Sweden - Switzerland - United Kingdom - United States of America

[www.st.com](http://www.st.com)